

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	59637	"8".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L2	52199	"68".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L3	21	(L1 or L2) and (pole with chang\$3) and (induction with motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L4	58	(L1 or L2) and (pole with switch\$4) and (induction with motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L5	17	(L1 or L2) and (pole with switch\$4) with (dehydration or spinning or drying)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L6	0	(L3 or L4 or L5) and @pd> "20070911"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L7	59637	"8".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L8	52199	"68".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L9	0	(L7 or L8) and (pole with motor) and speed and voltage and phase and @pd> "20070911"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L10	59637	"8".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L11	52199	"68".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07

L12	0	(L10 or L11) and (pole with motor) and (voltage with phase) and @pd>"20070911"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:07
L13	0	(L3 or L4 or L5) and @pd>"20070911"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/04/24 22:08

4/ 24/ 2008 10:08:52 PM

C:\ Documents and Settings\Jriggleman\ My Documents\ EAST\ Workspaces\ 10755472x.wsp